

FIELD INSPECTION REPORT

Project Name:	Mountain Valley Pipeline	Inspector:	Marshall Willis
Inspection Date:	Thursday, March 11, 2021	Project Contact:	Brian Clauto, Cory Chalmers
Spread G: Giles County	STA 11011+87 – 11065+00 MVP-GI-243.01 MVP-GI-245.01	Weather:	Dry

ACTIVE STAGE OF CONSTRUCTION: (Check all that apply)

- Tree Felling
 Clearing/Grubbing
 Grading
 Trenching
 Stringing/Welding
 Lowering/Backfilling
 Final Restoration
 Temp. Stabilization
 Perm. Stabilization
 Dormant

- | | | Yes | No | N/A |
|----|---|-------------------------------------|-------------------------------------|--------------------------|
| 1. | Are controls installed and implemented in accordance with the approved erosion and sediment control plan and stormwater management plans? | <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> |
| 2. | Are all control measures properly maintained in effective operating condition in accordance with good engineering practices and, where applicable, manufacturer specifications? | <input type="checkbox"/> | <input checked="" type="checkbox"/> | <input type="checkbox"/> |
| 3. | Areas of offsite sediment deposition observed? | <input type="checkbox"/> | <input checked="" type="checkbox"/> | <input type="checkbox"/> |

Comments: Inspected the following resources: S-RR4, S-RR5, S-IJ18 and S-IJ16-B.

Routine Maintenance: (72-Hour Deadline from Notification)
 - MVP-GI-243.01: CFS maintenance needed.

Recommended Corrective Action: Maintain and install all controls per the approved PSS&S.

Deadline: Within 72-Hour of Notification

The recommended corrective action deadline date applies to all conditions noted on this report unless otherwise noted. If listed condition(s) currently constitute non-compliance and/or corrective actions are not completed by the deadline, other enforcement actions may be issued to the entity responsible for ensuring compliance on the above project.

Inspector Signature: 

Date: Thursday, March 11, 2021

FIELD INSPECTION PHOTO LOG

Project Name: Mountain Valley Pipeline

Date: Thursday, March 11, 2021

Figure 1: MVP-GI-243.01 – CFS maintenance needed.

BRG: 244°SW (T) **LAT:** 37.326874 **LON:** -80.552590 ±32ft **ALT:** 2766ft



Figure 2: STA 11013+00 – Controls in place and functioning properly.

BRG: 119°SE (T) **LAT:** 37.325066 **LON:** -80.556952 ±5124ft **ALT:** 2570ft



Figure 3: STA 11029+00 – Controls in place and functioning properly.

BRG: 158°S (T) **LAT:** 37.322426 **LON:** -80.551258 ±16ft **ALT:** 2415ft



Figure 4: STA 11048+00 – Controls in place and functioning properly.

BRG: 115°SE (T) **LAT:** 37.318292 **LON:** -80.548327 ±98ft **ALT:** 2231ft

