

## FIELD INSPECTION REPORT

<b>Project Name:</b>	Mountain Valley Pipeline	<b>Inspector:</b>	Marshall Willis
<b>Inspection Date:</b>	Monday, April 5, 2021	<b>Project Contact:</b>	Brian Clauto, Cory Chalmers
<b>Spread G: Giles County</b>	STA 11158+50 – 11170+00 MVP-GI-256.02 MVP-GI-249.01	<b>Weather:</b>	Dry

**ACTIVE STAGE OF CONSTRUCTION:** (Check all that apply)

- Tree Felling     
  Clearing/Grubbing     
  Grading     
  Trenching     
  Stringing/Welding  
 Lowering/Backfilling     
  Final Restoration     
  Temp. Stabilization     
  Perm. Stabilization     
  Dormant

- |    |   | Yes                                 | No                                  | N/A                      |
|----|---|-------------------------------------|-------------------------------------|--------------------------|
| 1. | Are controls installed and implemented in accordance with the approved erosion and sediment control plan and stormwater management plans?                                       | <input checked="" type="checkbox"/> | <input type="checkbox"/>            | <input type="checkbox"/> |
| 2. | Are all control measures properly maintained in effective operating condition in accordance with good engineering practices and, where applicable, manufacturer specifications? | <input checked="" type="checkbox"/> | <input type="checkbox"/>            | <input type="checkbox"/> |
| 3. | Areas of offsite sediment deposition observed?  | <input type="checkbox"/>            | <input checked="" type="checkbox"/> | <input type="checkbox"/> |

**Comments:** Inspected the following resources: S-NN13, S-NN14 and S-NN17.

**Recommended Corrective Action:** N/A

**Deadline:** N/A

The recommended corrective action deadline date applies to all conditions noted on this report unless otherwise noted. If listed condition(s) currently constitute non-compliance and/or corrective actions are not completed by the deadline, other enforcement actions may be issued to the entity responsible for ensuring compliance on the above project.

**Inspector Signature:**



**Date:** Monday, April 5, 2021

## FIELD INSPECTION PHOTO LOG

**Project Name:** Mountain Valley Pipeline

**Date:** Monday, April 5, 2021

**Figure 1: MVP-GI-256.02** – Controls in place and functioning properly.  
 BRG: 226°SW (T) LAT: 37.304000 LON: -80.471603 ±5443ft ALT: 2088ft



**Figure 2: STA 11167+00** – PPL actively installing CWD and level spreader outlet.  
 BRG: 240°SW (T) LAT: 37.310146 LON: -80.514244 ±32ft ALT: 1868ft



**Figure 3: STA 11167+00** – PPL actively installing CWD and level spreader outlet.  
 BRG: 48°NE (T) LAT: 37.310492 LON: -80.514443 ±16ft ALT: 1840ft



**Figure 4: STA 11161+00** – Controls in place and functioning properly.  
 BRG: 299°NW (T) LAT: 37.310801 LON: -80.515844 ±541ft ALT: 1832ft

