

FIELD INSPECTION REPORT

Project Name:	Mountain Valley Pipeline	Inspector:	Marshall Willis
Inspection Date:	Tuesday, March 30, 2021	Project Contact:	Brian Clauto, Cory Chalmers
Spread G: Giles County	STA 11064+28 – 11151+27 MVP-GI-249 MCP-GI-245.01	Weather:	Dry

ACTIVE STAGE OF CONSTRUCTION: (Check all that apply)

- Tree Felling
 Clearing/Grubbing
 Grading
 Trenching
 Stringing/Welding
 Lowering/Backfilling
 Final Restoration
 Temp. Stabilization
 Perm. Stabilization
 Dormant

- | | | Yes | No | N/A |
|----|---|-------------------------------------|-------------------------------------|--------------------------|
| 1. | Are controls installed and implemented in accordance with the approved erosion and sediment control plan and stormwater management plans? | <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> |
| 2. | Are all control measures properly maintained in effective operating condition in accordance with good engineering practices and, where applicable, manufacturer specifications? | <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> |
| 3. | Areas of offsite sediment deposition observed? | <input type="checkbox"/> | <input checked="" type="checkbox"/> | <input type="checkbox"/> |

Comments: Inspected the following resources: S-IJ16a.

Recommended Corrective Action: N/A

Deadline: N/A

The recommended corrective action deadline date applies to all conditions noted on this report unless otherwise noted. If listed condition(s) currently constitute non-compliance and/or corrective actions are not completed by the deadline, other enforcement actions may be issued to the entity responsible for ensuring compliance on the above project.

Inspector Signature: _____



Date: Tuesday, March 30, 2021

FIELD INSPECTION PHOTO LOG

Project Name: Mountain Valley Pipeline

Date: Tuesday, March 30, 2021

Figure 1: STA 11148+00 – Controls in place and functioning properly.
 BRG: 153°SE (T) LAT: 37.306572 LON: -80.509770 ±11398ft ALT: 1865ft



Figure 2: STA 11139+00 – Controls in place and functioning properly.
 BRG: 305°NW (T) LAT: 37.313599 LON: -80.522308 ±16ft ALT: 2149ft



Figure 3: STA 11100+00 – Controls in place and functioning properly.
 BRG: 273°W (T) LAT: 37.313195 LON: -80.533283 ±32ft ALT: 1984ft



Figure 4: STA 11067+00 – Controls in place and functioning properly.
 BRG: 92°E (T) LAT: 37.306213 LON: -80.508641 ±13639ft ALT: 2168ft

