

FIELD INSPECTION REPORT

Project Name:	Mountain Valley Pipeline	Inspector:	Marshall Willis
Inspection Date:	Tuesday, April 27, 2021	Project Contact:	Brian Clauto, Cory Chalmers
Spread G: Giles County	STA 10971+74 – 11098+43 MVP-GI-242.01 MVP-GI-245.01	Weather:	Dry

ACTIVE STAGE OF CONSTRUCTION: (Check all that apply)

- Tree Felling
 Clearing/Grubbing
 Grading
 Trenching
 Stringing/Welding
 Lowering/Backfilling
 Final Restoration
 Temp. Stabilization
 Perm. Stabilization
 Dormant

- | | | Yes | No | N/A |
|----|---|-------------------------------------|-------------------------------------|--------------------------|
| 1. | Are controls installed and implemented in accordance with the approved erosion and sediment control plan and stormwater management plans? | <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> |
| 2. | Are all control measures properly maintained in effective operating condition in accordance with good engineering practices and, where applicable, manufacturer specifications? | <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> |
| 3. | Areas of offsite sediment deposition observed? | <input type="checkbox"/> | <input checked="" type="checkbox"/> | <input type="checkbox"/> |

Comments: Inspected the following resources: S-MN11, S-E24, S-E25, S-RR5, S-IJ18, S-IJ16b and S-IJ16a.

Recommended Corrective Action: N/A

Deadline: N/A

The recommended corrective action deadline date applies to all conditions noted on this report unless otherwise noted. If listed condition(s) currently constitute non-compliance and/or corrective actions are not completed by the deadline, other enforcement actions may be issued to the entity responsible for ensuring compliance on the above project.

Inspector Signature:



Date: Tuesday, April 27, 2021

FIELD INSPECTION PHOTO LOG

Project Name: Mountain Valley Pipeline

Date: Tuesday, April 27, 2021

Figure 1: STA 10992+00 – Controls in place and functioning properly.
BRG: 286°W (T) **LAT:** 37.325000 **LON:** -80.563064 ±16ft **ALT:** 2530ft



Figure 2: STA 11020+00 – Controls in place and functioning properly.
BRG: 266°W (T) **LAT:** 37.323524 **LON:** -80.554245 ±16ft **ALT:** 2459ft



Figure 3: STA 11033+00 – Controls in place and functioning properly.
BRG: 148°SE (T) **LAT:** 37.321152 **LON:** -80.550845 ±16ft **ALT:** 2386ft



Figure 4: STA 11045+00 – Controls in place and functioning properly.
BRG: 112°E (T) **LAT:** 37.326534 **LON:** -80.550608 ±9564ft **ALT:** 2346ft

