

FIELD INSPECTION REPORT

Project Name:	Mountain Valley Pipeline	Inspector:	Marshall Willis
Inspection Date:	Friday, June 11, 2021	Project Contact:	Brian Clauto, Cory Chalmers
Spread G: Giles County	STA 10929+71 – 11023+80 MVP-GI-244	Weather:	Wet

ACTIVE STAGE OF CONSTRUCTION: (Check all that apply)

- Tree Felling
 Clearing/Grubbing
 Grading
 Trenching
 Stringing/Welding
 Lowering/Backfilling
 Final Restoration
 Temp. Stabilization
 Perm. Stabilization
 Dormant

- | | | Yes | No | N/A |
|----|---|-------------------------------------|-------------------------------------|--------------------------|
| 1. | Are controls installed and implemented in accordance with the approved erosion and sediment control plan and stormwater management plans? | <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> |
| 2. | Are all control measures properly maintained in effective operating condition in accordance with good engineering practices and, where applicable, manufacturer specifications? | <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> |
| 3. | Areas of offsite sediment deposition observed? | <input type="checkbox"/> | <input checked="" type="checkbox"/> | <input type="checkbox"/> |

Comments: Inspected the following resources: S-E24, S-E25, S-RR5, S-IJ19 and S-IJ18.

Recommended Corrective Action: N/A

Deadline: N/A

The recommended corrective action deadline date applies to all conditions noted on this report unless otherwise noted. If listed condition(s) currently constitute non-compliance and/or corrective actions are not completed by the deadline, other enforcement actions may be issued to the entity responsible for ensuring compliance on the above project.

Inspector Signature:



Date: Friday, June 11, 2021

FIELD INSPECTION PHOTO LOG

Project Name: Mountain Valley Pipeline

Date: Friday, June 11, 2021

Figure 1: STA 11020+00 – Controls in place and functioning properly.
 BRG: 281°W (T) LAT: 37.323307 LON: -80.554028 ±16ft ALT: 2458ft



Figure 2: STA 10993+00 – Controls in place and functioning properly.
 BRG: 311°NW (T) LAT: 37.324776 LON: -80.562949 ±16ft ALT: 2587ft



Figure 3: STA 10970+00 – Controls in place and functioning properly.
 BRG: 277°W (T) LAT: 37.327311 LON: -80.570350 ±16ft ALT: 2433ft



Figure 4: STA 10937+00 – Controls in place and functioning properly.
 BRG: 291°W (T) LAT: 37.330321 LON: -80.580914 ±16ft ALT: 2283ft

