



Project Name:	Mountain Valley Pipeline	Inspector:	Matthew Grant
Inspection Date:	Thursday, May 27, 2021	Project Contact:	Brian Clauto
Spread G: Giles	AR GI 240, 258.04 ATWS 1057, 1373 St10690-10660 St11620-11600	Weather:	Dry

			St116	20-11600									
ACTIVE STAGE OF CONSTRUCTION: (Check all that apply)													
	Tree Fellin	ıg	$\boxtimes$	Clearing/Grubbing	$\boxtimes$	Grading		Trenching		Str	inging/Welding		
	Lowering/E	Backfilling		Final Grading		Temp. Stabilization		Perm. Stabilization	$\boxtimes$	Do	rmant		
									Yes	No	N/A		
	1.	1. Are controls installed and implemented in accordance with the approved erosion and sediment control plan and stormwater management plans?							$\boxtimes$				
	2.	Are all control measures properly maintained in effective operating condition in accordance with good engineering practices and, where applicable, manufacturer specifications?							$\boxtimes$				
	3.	Areas of	offsite	sediment deposition	observe	ed?				$\boxtimes$			
<ul> <li><u>Comments:</u> Inspected the following resources: S-RR13, S-RR14, S-006, S-G30.</li> <li>ECD's were in place and functioning at the designated crossings.</li> </ul>													
Routine Maintenance: ( <u>72-Hour Deadline</u> from Notification) - N/A													
Ineffective Controls: ( <u>24-Hour Deadline</u> from Notification) - N/A													
Recommended Corrective Action: N/A													
											_		

Deadline: N/A

The recommended corrective action deadline date applies to all conditions noted on this report unless otherwise noted. If listed condition(s) currently constitute non-compliance and/or corrective actions are not completed by the deadline, other enforcement actions may be issued to the entity responsible for ensuring compliance on the above project.

Inspector Signature: \_\_\_\_

Date: Thursday, May 27, 2021

## FIELD INSPECTION PHOTO LOG



Project Name: Mountain Valley Pipeline <u>Date</u>: Thursday, May 27, 2021

Figure 1: Installation of ECD at St10688+91.



Figure 2: Installation of temporary waterbar at St10676.



Figure 3: Designated crossing S-RR13, ECD's are in place.



Figure 4: Designated crossing S-006, ECD's are in place.

