

FIELD INSPECTION REPORT

Project Name:	Mountain Valley Pipeline	Inspector:	Matthew Grant
Inspection Date:	Wednesday, May 26, 2021	Project Contact:	Brian Clauto
Spread G: Giles	ATWS 466, 464, 1145, 1146 St10850-10858 St10802+81-10818+31 St11010-11025 AR GI 244, 241.03, 241.02	Weather:	Dry

ACTIVE STAGE OF CONSTRUCTION: (Check all that apply)

- Tree Felling
 Clearing/Grubbing
 Grading
 Trenching
 Stringing/Welding
 Lowering/Backfilling
 Final Grading
 Temp. Stabilization
 Perm. Stabilization
 Dormant

- | | Yes | No | N/A |
|--|-------------------------------------|-------------------------------------|--------------------------|
| 1. Are controls installed and implemented in accordance with the approved erosion and sediment control plan and stormwater management plans? | <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> |
| 2. Are all control measures properly maintained in effective operating condition in accordance with good engineering practices and, where applicable, manufacturer specifications? | <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> |
| 3. Areas of offsite sediment deposition observed? | <input type="checkbox"/> | <input checked="" type="checkbox"/> | <input type="checkbox"/> |

- Comments: Inspected the following resources: S-E25, S-E24, S-YZ1, P-YZ1, S-Z14, S-Z13
- ECD's were in place and functioning at the designated crossings.

Routine Maintenance: (72-Hour Deadline from Notification)

- N/A


Ineffective Controls: (24-Hour Deadline from Notification)

- N/A

Recommended Corrective Action: N/A

Deadline: N/A

The recommended corrective action deadline date applies to all conditions noted on this report unless otherwise noted. If listed condition(s) currently constitute non-compliance and/or corrective actions are not completed by the deadline, other enforcement actions may be issued to the entity responsible for ensuring compliance on the above project.

Inspector Signature: _____  _____

Date: Wednesday, May 26, 2021

FIELD INSPECTION PHOTO LOG

Project Name: Mountain Valley Pipeline

Date: Wednesday, May 26, 2021

<p>▪ Figure 1: St10977 ECD's have been installed.</p> <div style="border: 1px solid black; padding: 5px; margin-bottom: 5px;"> <p style="text-align: center;">South East Elevation</p> <p style="text-align: center;">☉ 306°NW (T) ● 37°19'35"N, 80°34'3"W ±164ft ▲ 2343ft</p>  </div>	<p>▪ Figure 2: St10977 ECD's have been installed.</p> <div style="border: 1px solid black; padding: 5px; margin-bottom: 5px;"> <p style="text-align: center;">East Elevation</p> <p style="text-align: center;">☉ 249°W (T) ● 37°19'35"N, 80°34'4"W ±32ft ▲ 2299ft</p>  </div>
<p>▪ Figure 3: St10966+50 Sensitive resource area is protected.</p> <div style="border: 1px solid black; padding: 5px; margin-bottom: 5px;"> <p style="text-align: center;">South East Elevation</p> <p style="text-align: center;">☉ 324°NW (T) ● 37°19'38"N, 80°34'17"W ±98ft ▲ 2297ft</p>  </div>	<p>▪ Figure 4: St10858+73 grading activity.</p> <div style="border: 1px solid black; padding: 5px; margin-bottom: 5px;"> <p style="text-align: center;">East Elevation</p> <p style="text-align: center;">☉ 289°W (T) ● 37°20'14"N, 80°36'16"W ±16ft ▲ 2294ft</p>  </div>