

FIELD INSPECTION REPORT

Project Name:	Mountain Valley Pipeline	Inspector:	Marshall Willis
Inspection Date:	Tuesday, May 18, 2021	Project Contact:	Brian Clauto, Cory Chalmers
Spread G: Montgomery County	STA 11596+94 - 11618+91 MVP-MN-258.05	Weather:	Wet

IVIOI	itgoillery C	ounty	IVI V 🗁 -I	WIN-236.03									
	ACTI	VE STAGE	OF C	ONSTRUCTION: (C	Check a	II that apply	<i>(</i>)						
	Tree Felling		☐ Clearing/Grubbing			☐ Grading		☐ Trenching			Stri	nging/Welding	
	Lowering/B	Backfilling		Final Restoration		Temp. St	abilization		Perm. Stabilization	n. Stabilization 🗵 Dormant			
										Yes	No	N/A	
	Are controls installed and implemented in accordance with the approved erosion and sediment control plan and stormwater management plans?								\boxtimes				
Are all control measures properly maintained in effective operating condition in accordance with good engineering practices and, where applicable, manufacturer specifications?									\boxtimes				
	3.	Areas of o	ffsite s	sediment deposition	observe	÷d?					\boxtimes		
	Com	nments: Ins	pecte	d the following resou	ırces: S	-006, S-Ri	R13 and S-F	RR14.					
	Rec	ommende	ed Co	orrective Action:	N/A								
	<u>Dead</u>	dline: N/	<u>A</u>										
The recommended corrective action deadline date applies to all conditions noted on this report unless otherwise noted. If listed condition(s) currently constitute non-compliance and/or corrective actions are not completed by the deadline, other enforcement actions may be issued to the entity responsible for ensuring compliance on the above project.													
	Inspe	ector Sigr	nature	e: Makshu	U K	Willia	2						
	Date:	: Tuesd	lay, M	lay 18, 2021									




FIELD INSPECTION PHOTO LOG

Project Name: Mountain Valley Pipeline

Date: Tuesday, May 18, 2021

Figure 2: Stream S-RR14 - Controls in place and functioning



BRG: 128°SE (T) LAT: 37.314629 LON: -80.402699 ±16ft ALT: 1878ft





<u>Figure 3</u>: **STA 11608+00** – Controls in place and functioning properly.

BRG: 92°E (T) LAT: 37.313667 LON: -80.404540 ±32ft ALT: 1912ft



<u>Figure 4</u>: **Stream S-O06** – Controls in place and functioning properly around Craig Creek.

BRG: 261°W (T) LAT: 37.313637 LON: -80.404490 ±16ft ALT: 1901ft