

FIELD INSPECTION REPORT

Project Name:	Mountain Valley Pipeline	Inspector:	Marshall Willis
Inspection Date:	Monday, May 17, 2021	Project Contact:	Brian Clauto, Cory Chalmers
Spread G: Giles County	STA 10749+71 – 10789+05 MVP-GI-241.01/241.04/241.03	Weather:	Rainy

ACTIVE STAGE OF CONSTRUCTION: (Check all that apply)

- Tree Felling
 Clearing/Grubbing
 Grading
 Trenching
 Stringing/Welding
 Lowering/Backfilling
 Final Restoration
 Temp. Stabilization
 Perm. Stabilization
 Dormant

- | | Yes | No | N/A |
|--|-------------------------------------|-------------------------------------|--------------------------|
| 1. Are controls installed and implemented in accordance with the approved erosion and sediment control plan and stormwater management plans? | <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> |
| 2. Are all control measures properly maintained in effective operating condition in accordance with good engineering practices and, where applicable, manufacturer specifications? | <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> |
| 3. Areas of offsite sediment deposition observed? | <input type="checkbox"/> | <input checked="" type="checkbox"/> | <input type="checkbox"/> |

Comments: Inspected the following resources: S-G35.

Recommended Corrective Action: N/A

Deadline: N/A

The recommended corrective action deadline date applies to all conditions noted on this report unless otherwise noted. If listed condition(s) currently constitute non-compliance and/or corrective actions are not completed by the deadline, other enforcement actions may be issued to the entity responsible for ensuring compliance on the above project.

Inspector Signature: _____



Date: Monday, May 17, 2021

FIELD INSPECTION PHOTO LOG

Project Name: Mountain Valley Pipeline

Date: Monday, May 17, 2021

Figure 1: STA 10748+00 – Controls in place and functioning properly.
BRG: 321°NW (T) **LAT:** 37.345255 **LON:** -80.636571 ±16ft **ALT:** 2301ft



Figure 2: STA 10752+00 – Controls in place and functioning properly.
BRG: 92°E (T) **LAT:** 37.344586 **LON:** -80.635579 ±16ft **ALT:** 2285ft



Figure 3: STA 10756+00 – Controls in place and functioning properly.
BRG: 85°E (T) **LAT:** 37.344733 **LON:** -80.634306 ±16ft **ALT:** 2211ft



Figure 4: Stream S-G35 – Controls in place and functioning properly.
BRG: 303°NW (T) **LAT:** 37.344790 **LON:** -80.633358 ±32ft **ALT:** 2124ft

