

## FIELD INSPECTION REPORT

<b>Project Name:</b>	Mountain Valley Pipeline	<b>Inspector:</b>	Marshall Willis
<b>Inspection Date:</b>	Tuesday, May 11, 2021	<b>Project Contact:</b>	Brian Clauto, Cory Chalmers
<b>Spread G: Giles County</b>	STA 10674+92 – 10707+00 MVP-GI-241/241.01/241.03/241.04	<b>Weather:</b>	Dry

**ACTIVE STAGE OF CONSTRUCTION:** (Check all that apply)

- Tree Felling     
  Clearing/Grubbing     
  Grading     
  Trenching     
  Stringing/Welding  
 Lowering/Backfilling     
  Final Restoration     
  Temp. Stabilization     
  Perm. Stabilization     
  Dormant

- |    |   | Yes                                 | No                                  | N/A                      |
|----|---|-------------------------------------|-------------------------------------|--------------------------|
| 1. | Are controls installed and implemented in accordance with the approved erosion and sediment control plan and stormwater management plans?                                       | <input type="checkbox"/>            | <input checked="" type="checkbox"/> | <input type="checkbox"/> |
| 2. | Are all control measures properly maintained in effective operating condition in accordance with good engineering practices and, where applicable, manufacturer specifications? | <input checked="" type="checkbox"/> | <input type="checkbox"/>            | <input type="checkbox"/> |
| 3. | Areas of offsite sediment deposition observed?  | <input type="checkbox"/>            | <input checked="" type="checkbox"/> | <input type="checkbox"/> |

**Comments:** Inspected the following resources: S-G30 and S-G32.

**Ineffective Controls:** (24-Hour Deadline from Notification)

- STA 10677+00: Topsoil waterbar does not have end-treatment.
- STA 10677+61: Topsoil waterbar does not have end-treatment.
- STA 10677+93: Topsoil waterbar does not have end-treatment.

**Recommended Corrective Action:** Maintain and install all controls per the approved PSS&S.

**Deadline:** Within 24-Hour of Notification

The recommended corrective action deadline date applies to all conditions noted on this report unless otherwise noted. If listed condition(s) currently constitute non-compliance and/or corrective actions are not completed by the deadline, other enforcement actions may be issued to the entity responsible for ensuring compliance on the above project.

**Inspector Signature:** 

**Date:** Tuesday, May 11, 2021

## FIELD INSPECTION PHOTO LOG

**Project Name:** Mountain Valley Pipeline

**Date:** Tuesday, May 11, 2021

**Figure 1: STA 10677+00** – Topsoil waterbar does not have end-treatment.

**BRG:** 147°SE (T) **LAT:** 37.350207 **LON:** -80.659164 ±32ft **ALT:** 2116ft



**Figure 2: STA 10677+61** – Topsoil waterbar does not have end-treatment.

**BRG:** 116°SE (T) **LAT:** 37.349931 **LON:** -80.658916 ±32ft **ALT:** 2094ft



**Figure 3: STA 10677+93** – Topsoil waterbar does not have end-treatment.

**BRG:** 140°SE (T) **LAT:** 37.350121 **LON:** -80.658662 ±16ft **ALT:** 2104ft



**Figure 4: Stream S-G30** – Controls in place and functioning properly.

**BRG:** 271°W (T) **LAT:** 37.350379 **LON:** -80.657914 ±16ft **ALT:** 2074ft

