

FIELD INSPECTION REPORT

Project Name:	Mountain Valley Pipeline	Inspector:	Marshall Willis
Inspection Date:	Wednesday, May 5, 2021	Project Contact:	Brian Clauto, Cory Chalmers
Spread G: Craig County	STA 11524+16 – 11471+52 MVP-CR-258.02 MVP-CR-258.01	Weather:	Wet

ACTIVE STAGE OF CONSTRUCTION: (Check all that apply)

- Tree Felling
 Clearing/Grubbing
 Grading
 Trenching
 Stringing/Welding
 Lowering/Backfilling
 Final Restoration
 Temp. Stabilization
 Perm. Stabilization
 Dormant

- | | | Yes | No | N/A |
|----|---|-------------------------------------|-------------------------------------|--------------------------|
| 1. | Are controls installed and implemented in accordance with the approved erosion and sediment control plan and stormwater management plans? | <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> |
| 2. | Are all control measures properly maintained in effective operating condition in accordance with good engineering practices and, where applicable, manufacturer specifications? | <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> |
| 3. | Areas of offsite sediment deposition observed? | <input type="checkbox"/> | <input checked="" type="checkbox"/> | <input type="checkbox"/> |

Comments: Inspected the following resources: S-QQ2, S-PP4, S-PP3 and S-PP1.

Recommended Corrective Action: N/A

Deadline: N/A

The recommended corrective action deadline date applies to all conditions noted on this report unless otherwise noted. If listed condition(s) currently constitute non-compliance and/or corrective actions are not completed by the deadline, other enforcement actions may be issued to the entity responsible for ensuring compliance on the above project.

Inspector Signature: 

Date: Wednesday, May 5, 2021

FIELD INSPECTION PHOTO LOG

Project Name: Mountain Valley Pipeline

Date: Wednesday, May 5, 2021

Figure 1: Stream S-QQ2 – Controls in place and functioning properly around stream crossing. (Sinking Creek)
BRG: 178°S (T) **LAT:** 37.333126 **LON:** -80.431150 ±541ft **ALT:** 2008ft



Figure 2: STA 11521+00 – Controls in place and functioning properly.
BRG: 263°W (T) **LAT:** 37.328683 **LON:** -80.421833 ±16ft **ALT:** 2248ft



Figure 3: STA 11495+00 – Controls in place and functioning properly.
BRG: 230°SW (T) **LAT:** 37.325289 **LON:** -80.429496 ±16ft **ALT:** 2288ft



Figure 4: STA 11478+00 – Controls in place and functioning properly.
BRG: 65°NE (T) **LAT:** 37.280701 **LON:** -80.388092 ±6562ft **ALT:** 2148ft

