



Project Name:	Mountain Valley Pipeline	Inspector:	Matthew Grant		
Inspection Date:	Tuesday, April 27, 2021	Project Contact:	Brian Clauto		
Spread G: Giles	ST11300-11353+60 10970-11062 ATWS 633A, 633 AR 253.02, 242.01	Weather:	Dry		

Spread G: Giles	10970-11062 ATWS 633A, 633 AR 253.02, 242.01		Weather:		Dry						
ACTIVE STAGE OF CONSTRUCTION: (Check all that apply)											
☐ Tree Felling	☐ Clearing/Grubbing	⊠ Gra	ding	☐ Trench	ning	\boxtimes	Strir	nging/Welding			
☐ Lowering/Backfilling	☐ Final Grading	☐ Tem	np. Stabilization	☐ Perm.	Stabilization	ı 🗆	Dor	mant			
						Yes	No	N/A			
Are controls installed and implemented in accordance with the approved erosion and sediment control plan and stormwater management plans?						\boxtimes					
Are all control measures properly maintained in effective operating condition in accordance with good engineering practices and, where applicable, manufacturer specifications?											
Areas of offsite sediment deposition observed?							\boxtimes				
 <u>Comments:</u> Inspected the following resources: S-MM17, W-MM10, S-NN12, S-NN11, S-MN11, S-E24, S-E25, S-RR5, S-PA07, S-IJ18, S-IJ65, S-IJ16B ECD's were in place and functioning at the designated crossings. 											
Routine Maintenance: (<u>72-Hour Deadline</u> from Notification) - N/A											
Ineffective Controls: (<u>24-Hour Deadline</u> from Notification) - N/A											
Recommended Corrective Action: N/A											

Deadline: N/A

The recommended corrective action deadline date applies to all conditions noted on this report unless otherwise noted. If listed condition(s) currently constitute non-compliance and/or corrective actions are not completed by the deadline, other enforcement actions may be issued to the entity responsible for ensuring compliance on the above project.

Inspector Signature: _____

Date: Tuesday, April 27, 2021



FIELD INSPECTION PHOTO LOG

Project Name: Mountain Valley Pipeline <u>Date</u>: Tuesday, April 27, 2021

Figure 1: Near St11301+00 pipe is strung and welding crews on site, ECD's are in place.



Figure 2: Designated crossing S-NN11, ECD's are in place.



Figure 3: Near St11056 the karsts area is protected by ECD's.



<u>Figure 4</u>: Above designated crossing S-RR5, additional ECD crews are mobilizing.

