



Project Name:	Mountain Valley Pipeline	Inspector:	Matthew Grant
Inspection Date:	Monday, April 26, 2021	Project Contact:	Brian Clauto
Spread G: Giles	ST11254+66-11168 ATWS 1347, 1464 AR MLV 25, GI 249.01	Weather:	Dry

Gile	es			LV 25, GI 249.01			Weather.			D, y			
ACTIVE STAGE OF CONSTRUCTION: (Check all that apply)													
	Tree Felling		☐ Clearing/Grubbing ☒ Grad		ding 🗌 Trenct		Trench	ing	\boxtimes	Stri	inging/Welding		
	Lowering/Ba	ackfilling		Final Grading		Tem	p. Stabilization		Perm.	Stabilization		Doi	rmant
											Yes	No	N/A
	1. Are controls installed and implemented in accordance with the approved erosion and sediment control plan and stormwater management plans?								and				
	Are all control measures properly maintained in effective operating condition in accordance with good engineering practices and, where applicable, manufacturer specifications?										\boxtimes		
	3.	Areas of	offsite	sediment deposition o	observe	ed?						\boxtimes	
 <u>Comments:</u> Inspected the following resources: S-YZ6, W-RR1b ECD's were in place and functioning at the designated crossings. 													
Routine Maintenance: (<u>72-Hour Deadline</u> from Notification) - N/A													
Ineffective Controls: (<u>24-Hour Deadline</u> from Notification) - N/A													
Recommended Corrective Action: N/A													

Deadline: N/A

The recommended corrective action deadline date applies to all conditions noted on this report unless otherwise noted. If listed condition(s) currently constitute non-compliance and/or corrective actions are not completed by the deadline, other enforcement actions may be issued to the entity responsible for ensuring compliance on the above project.

Inspector Signature: _____

Date: Monday, April 26, 2021



FIELD INSPECTION PHOTO LOG

Project Name: Mountain Valley Pipeline Date: Monday, April 26, 2021

Figure 1: Near St11233, pipe has been strung and ECD's are in place.



Figure 2: Near St11246+83, area has been stabilized and ECD's are in place.



 Figure 3: Near St11190, pipe has been strung and ECD's are in place for active construction.



 <u>Figure 4</u>: Designated crossing S-YZ6 &W-RR1b, fell trees remain in place.

