

FIELD INSPECTION REPORT

Project Name:	Mountain Valley Pipeline	Inspector:	Marshall Willis
Inspection Date:	Friday, June 25, 2021	Project Contact:	Brian Clauto, Cory Chalmers
Spread G: Giles County	STA 10656+80 – 10675+00 STA 10749+41 – 10774+15 MVP-GI-240	Weather:	Dry

ACTIVE STAGE OF CONSTRUCTION: (Check all that apply)

- Tree Felling
 Clearing/Grubbing
 Grading
 Trenching
 Stringing/Welding
 Lowering/Backfilling
 Final Restoration
 Temp. Stabilization
 Perm. Stabilization
 Dormant

- | | | Yes | No | N/A |
|----|---|-------------------------------------|-------------------------------------|--------------------------|
| 1. | Are controls installed and implemented in accordance with the approved erosion and sediment control plan and stormwater management plans? | <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> |
| 2. | Are all control measures properly maintained in effective operating condition in accordance with good engineering practices and, where applicable, manufacturer specifications? | <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> |
| 3. | Areas of offsite sediment deposition observed? | <input type="checkbox"/> | <input checked="" type="checkbox"/> | <input type="checkbox"/> |

Comments: Inspected the following resources: S-G35, S-SS4 and S-Z9.

Recommended Corrective Action: N/A

Deadline: N/A

The recommended corrective action deadline date applies to all conditions noted on this report unless otherwise noted. If listed condition(s) currently constitute non-compliance and/or corrective actions are not completed by the deadline, other enforcement actions may be issued to the entity responsible for ensuring compliance on the above project.

Inspector Signature:



Date: Friday, June 25, 2021

FIELD INSPECTION PHOTO LOG

Project Name: Mountain Valley Pipeline

Date: Friday, June 25, 2021

Figure 1: STA 10670+00 – Controls in place and functioning properly.
 BRG: 142°SE (T) LAT: 37.351245 LON: -80.660704 ±16ft ALT: 2256ft



Figure 2: STA 10664+00 – Controls in place and functioning properly.
 BRG: 307°NW (T) LAT: 37.352778 LON: -80.661354 ±16ft ALT: 2203ft



Figure 3: STA 10751+77 – Controls in place and functioning properly.
 BRG: 102°E (T) LAT: 37.344677 LON: -80.635558 ±98ft ALT: 2229ft



Figure 4: STA 10764+00 – Controls in place and functioning properly.
 BRG: 80°E (T) LAT: 37.343719 LON: -80.632378 ±1384ft ALT: 2078ft

