

FIELD INSPECTION

Project Name:	Mountain Valley Pipeline	Inspector:	Matthew Grant
Inspection Date:	Tuesday, July 9, 2019	Project Contact:	Brian Clauto
Spread: Giles County AR 25 MP 212 St11227 AR 28 Montgomery County MLV 26 MP222- 223 St11766+76-11804	Spread G	Weather (Wet/Dry/Rain):	Dry

STAGE OF CONSTRUCTION: (Check all that apply)

- Clearing Rough Grading Trench Excavation Pipe Assembly, Testing & Installation
 Backfilling and Grade Restoration Final Grading & Stabilization Other: Dormant

- | | | Yes | No | N/A |
|---|---|-------------------------------------|-------------------------------------|--------------------------|
| 1 | Are controls installed and implemented in accordance with the approved erosion and sediment control plan and stormwater management plans? | <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> |
| 2 | Are all control measures properly maintained in effective operating condition in accordance with good engineering practices and, where applicable, manufacturer specifications? | <input type="checkbox"/> | <input checked="" type="checkbox"/> | <input type="checkbox"/> |
| 3 | Areas of offsite sediment deposition were observed? | <input type="checkbox"/> | <input checked="" type="checkbox"/> | <input type="checkbox"/> |

Comments:

- Designated stream inspected included: W-IJ 46 ECD controls were in place and functioning at crossing.
- St11766+76 through 11764 lacks adequate temporary stabilization
- St11764+00 ECD j hook requires maintenance
- St11783+95 erosion and inadequate stabilization near ECD sump

Recommended Corrective Action: Maintain all controls per the approved plan and specs

Deadline: Within 24hr notification

The recommended corrective action deadline date applies to all conditions noted on this report unless otherwise noted. If listed condition(s) currently constitute non-compliance and/or corrective actions are not completed by the deadline, other enforcement actions may be issued to the entity responsible for ensuring compliance on the above project.

Inspector Signature: Matthew Grant Date: 7/22/19

FIELD INSPECTION PHOTO LOG

Project Name: Mountain Valley Pipeline

Date: Tuesday, July 9, 2019

- Fig. 1. Designated stream W-IJ 46 ECD controls were in place and functioning at crossing



- Fig. 2. St11766+76 through 11764 lacks adequate temporary stabilization



- Fig. 3. St11764+00 ECD j hook requires maintenance



- Fig. 4. St11783+95 erosion and inadequate stabilization near ECD sump

