



Project Name:	Mountain Valley Pipeline	Inspector:	Matthew Grant
Inspection Date:	Wednesday, June 30, 2021	Project Contact:	Brian Clauto
Spread G: Giles	AR GI 256.02 ATWS 1147 St 11328+63-11354+28	Weather:	Dry

			St 11.	328+63-11334+28								
ACTIVE STAGE OF CONSTRUCTION: (Check all that apply)												
	Tree Fellin	g		Clearing/Grubbing	$\boxtimes$	Grading		Trenching		Stri	nging/Welding	
	☐ Lowering/Backfilling [			Final Grading		Temp. Stabilization		Perm. Stabilization	n 🗆	Dor	mant	
									Yes	No	N/A	
Are controls installed and implemented in accordance with the approved erosion and sediment control plan and stormwater management plans?												
	2.	Are all control measures properly maintained in effective operating condition in accordance with good engineering practices and, where applicable, manufacturer specifications?						$\boxtimes$				
	3.	Areas of o	ffsite	sediment deposition o	bserve	ed?				$\boxtimes$		
<ul> <li><u>Comments:</u> Inspected the following resources: S-NN13, S-NN11</li> <li>ECD's were in place and functioning at the designated crossings for active construction.</li> </ul>												
Routine Maintenance: ( <u>72-Hour Deadline</u> from Notification) - N/A												
Ineffective Controls: (24-Hour Deadline from Notification) - N/A												
Recommended Corrective Action: N/A												
											_	

**Deadline:** N/A

The recommended corrective action deadline date applies to all conditions noted on this report unless otherwise noted. If listed condition(s) currently constitute non-compliance and/or corrective actions are not completed by the deadline, other enforcement actions may be issued to the entity responsible for ensuring compliance on the above project.

Inspector Signature: \_\_\_\_

Date: Wednesday, June 30, 2021

## FIELD INSPECTION PHOTO LOG



Project Name: Mountain Valley Pipeline <u>Date</u>: Wednesday, June 30, 2021

Figure 1: Designated crossing S-NN11



Figure 2:Designated crossing S-NN11



Figure 3: St 11328+63 ECD's are in place.



Figure 4: St 11342 ECD's are in place.

