



Project Name:	Mountain Valley Pipeline	Inspector:	Matthew Grant
Inspection Date:	Tuesday, February 21, 2023	Project Contact:	Brian Clauto
Spread G: Giles	St10820-10858 ATWS 466 AR GI 241.03	Weather:	Dry

ACTIVE STAGE OF CONSTRUCTION: (Check all that apply)												
	Tree Fellin	g		Clearing/Grubbing		Grading			Trenching		Strir	nging/Welding
☐ Lowering/Backfilling		Backfilling		Final Grading	inal Grading 🔲 Temp. Stabilization 🗀 Perm. Stabilizatio		Perm. Stabilization	\boxtimes	Dor	mant		
										Yes	No	N/A
	1.			alled and implemente I plan and stormwater			appro	oved (erosion and	\boxtimes		
	2.	Are all con with good	trol m engine	easures properly mai eering practices and,	ntained where	d in effective opera applicable, manuf	ating c acture	ondit r spe	ion in accordance cifications?	\boxtimes		
	3.	Areas of o	ffsite s	sediment deposition o	bserve	ed?					\boxtimes	
				lowing resources: S-\ unctioning at the de								
Ro	utine Mainte - N/A	enance: (<u>72</u>	?-Hour	<u>Deadline</u> from Notific	cation)							
Ineffective Controls: (<u>24-Hour Deadline</u> from Notification) - N/A												
Recommended Corrective Action: N/A												
												_
Deadline: N/A												
The recommended corrective action deadline date applies to all conditions noted on this report unless otherwise noted. If listed condition(s) currently constitute non-compliance and/or corrective actions are not completed by the deadline, other enforcement actions may be issued to the entity responsible for ensuring compliance on the above project.												

Inspector Signature: ____

Tuesday, February 21, 2023

Date:

FIELD INSPECTION PHOTO LOG



Project Name: Mountain Valley Pipeline <u>Date</u>: Tuesday, February 21, 2023



Figure 2: Designated crossing S-A33&34, ECD's are in place.



Figure 3: St10830 ECD's are in place.



Figure 4: AR-GI 241.03 ECD's are in place.

