

# FIELD INSPECTION REPORT

<b>Project Name:</b>	Mountain Valley Pipeline	<b>Inspector:</b>	Matthew Grant
<b>Inspection Date:</b>	Wednesday, September 21, 2022	<b>Project Contact:</b>	Brian Clauto
<b>Spread G: Giles</b>	AR GI 240, 240.01 ATWS 1335, 816, 471, 1331, 1333, 1332, 1360 St10656+46-10700, 10926+30- 10930	<b>Weather:</b>	Dry

**ACTIVE STAGE OF CONSTRUCTION:** (Check all that apply)

- Tree Felling     
  Clearing/Grubbing     
  Grading     
  Trenching     
  Stringing/Welding  
 Lowering/Backfilling     
  Final Grading     
  Temp. Stabilization     
  Perm. Stabilization     
  Dormant

- |  | Yes                                 | No                                  | N/A                      |
|--|-------------------------------------|-------------------------------------|--------------------------|
| 1. Are controls installed and implemented in accordance with the approved erosion and sediment control plan and stormwater management plans?                                       | <input checked="" type="checkbox"/> | <input type="checkbox"/>            | <input type="checkbox"/> |
| 2. Are all control measures properly maintained in effective operating condition in accordance with good engineering practices and, where applicable, manufacturer specifications? | <input checked="" type="checkbox"/> | <input type="checkbox"/>            | <input type="checkbox"/> |
| 3. Areas of offsite sediment deposition observed?  | <input type="checkbox"/>            | <input checked="" type="checkbox"/> | <input type="checkbox"/> |

- Comments: Inspected the following resources: S-A32, S-Y2, S-Y3, S-G30, S-G32
- ECD's were in place and functioning at the designated crossings.

**Routine Maintenance:** (72-Hour Deadline from Notification)  
- N/A

**Ineffective Controls:** (24-Hour Deadline from Notification)  
- N/A

**Recommended Corrective Action:** N/A

**Deadline:** N/A

The recommended corrective action deadline date applies to all conditions noted on this report unless otherwise noted. If listed condition(s) currently constitute non-compliance and/or corrective actions are not completed by the deadline, other enforcement actions may be issued to the entity responsible for ensuring compliance on the above project.

**Inspector Signature:** \_\_\_\_\_  \_\_\_\_\_

**Date:** Wednesday, September 21, 2022

# FIELD INSPECTION PHOTO LOG

**Project Name:** Mountain Valley Pipeline

**Date:** Wednesday, September 21, 2022

Figure 1: Designated crossing S-A32, ECD's are in place.



Figure 2: Designated crossing S-G30, ECD's are in place.



Figure 3: Designated crossing S-G32, ECD's are in place.



Figure 4: Designated crossing S-Y2, ECD's are in place.

