

FIELD INSPECTION REPORT

Project Name:	Mountain Valley Pipeline	Inspector:	Matthew Grant
Inspection Date:	Monday, March 13, 2023	Project Contact:	Brian Clauto
Spread G: Giles	St 10818-10802+06 ATWS 464, 1333, 471 AR GI 241.02, 241.03	Weather:	Wet

ACTIVE STAGE OF CONSTRUCTION: (Check all that apply)

- | | | | | |
|---|--|--|--|---|
| <input type="checkbox"/> Tree Felling | <input type="checkbox"/> Clearing/Grubbing | <input type="checkbox"/> Grading | <input type="checkbox"/> Trenching | <input type="checkbox"/> Stringing/Welding |
| <input type="checkbox"/> Lowering/Backfilling | <input type="checkbox"/> Final Grading | <input type="checkbox"/> Temp. Stabilization | <input type="checkbox"/> Perm. Stabilization | <input checked="" type="checkbox"/> Dormant |

	Yes	No	N/A
1. Are controls installed and implemented in accordance with the approved erosion and sediment control plan and stormwater management plans?	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
2. Are all control measures properly maintained in effective operating condition in accordance with good engineering practices and, where applicable, manufacturer specifications?	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
3. Areas of offsite sediment deposition observed?	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>

- **Comments:** Inspected the following resources: S-YZ1, S-Z14, S-Z13, S-A32, S-Y2, S-Y3
- ECD's were in place and functioning at the designated crossings.

Routine Maintenance: (*72-Hour Deadline from Notification*)

- N/A

Ineffective Controls: (*24-Hour Deadline from Notification*)

- N/A

Recommended Corrective Action: N/A

Deadline: N/A

The recommended corrective action deadline date applies to all conditions noted on this report unless otherwise noted. If listed condition(s) currently constitute non-compliance and/or corrective actions are not completed by the deadline, other enforcement actions may be issued to the entity responsible for ensuring compliance on the above project.

Inspector Signature: _____  _____

Date: Monday, March 13, 2023

FIELD INSPECTION PHOTO LOG

Project Name: Mountain Valley Pipeline

Date: Monday, March 13, 2023

Figure 1: Designated crossing S-A32, ECD's are in place.



Figure 2: Designated crossing S-Z14, ECD's are in place.



Figure 3: St10807 ECD's are in place.



Figure 4: St10815 ECD's are in place.

