# FIELD INSPECTION REPORT



Project Name:	Mountain Valley Pipeline	Inspector: Matthew 0		Frant		
Inspection Date:	Monday, March 20, 2023	Project Contact:	Brian Clauto			
Spread G: Montgomery	St 11767-11900 ATWS 1487, 1457, 1456 AR MN 266.03, MLV 26	Weather:	Dry			
ACTIVE STAGE OF CONSTRUCTION: (Check all that apply)						
Tree Felling	Tree Felling		ning	Stringing/Welding		
□ Lowering/Backfilling □ Final Grading □ Temp. Stabilization □ Perm. Stabilization ⊠ Dormant						mant
				Yes	No	N/A
<ol> <li>Are controls installed and implemented in accordance with the approved erosion and sediment control plan and stormwater management plans?</li> </ol>				$\boxtimes$		
2. Are all control measures properly maintained in effective operating condition in accordance with good engineering practices and, where applicable, manufacturer specifications?				$\boxtimes$		
3. Areas of	offsite sediment deposition observed?				$\boxtimes$	
<ul> <li><u>Comments:</u> Inspected the following resources: S-IJ52, W-IJ46</li> <li>ECD's were in place and functioning at the designated crossings.</li> <li>Routine Maintenance: (<u>72-Hour Deadline</u> from Notification)         <ul> <li>N/A</li> </ul> </li> <li>Ineffective Controls: (<u>24-Hour Deadline</u> from Notification)             <ul> <li>N/A</li> </ul> </li> <li>Recommended Corrective Action: N/A</li> </ul>						

### Deadline: N/A

The recommended corrective action deadline date applies to all conditions noted on this report unless otherwise noted. If listed condition(s) currently constitute non-compliance and/or corrective actions are not completed by the deadline, other enforcement actions may be issued to the entity responsible for ensuring compliance on the above project.

Inspector Signature: \_\_\_\_ Patter Matter

Date: Monday, March 20, 2023

## FIELD INSPECTION PHOTO LOG



#### Project Name: Mountain Valley Pipeline

### Date: Monday, March 20, 2023

