

## FIELD INSPECTION REPORT

<b>Project Name:</b>	Mountain Valley Pipeline	<b>Inspector:</b>	Marshall Willis
<b>Inspection Date:</b>	Tuesday, May 2, 2023	<b>Project Contact:</b>	Brian Clauto, Cory Chalmers
<b>Spread G: Giles County</b>	STA 11023+80 – 11098+47 MVP-GI-244 MVP-GI-245.02	<b>Weather:</b>	Dry

**ACTIVE STAGE OF CONSTRUCTION:** (Check all that apply)

- Tree Felling     
  Clearing/Grubbing     
  Grading     
  Trenching     
  Stringing/Welding  
 Lowering/Backfilling     
  Final Restoration     
  Temp. Stabilization     
  Perm. Stabilization     
 Dormant

- |    |   | Yes                                 | No                                  | N/A                      |
|----|---|-------------------------------------|-------------------------------------|--------------------------|
| 1. | Are controls installed and implemented in accordance with the approved erosion and sediment control plan and stormwater management plans?                                       | <input checked="" type="checkbox"/> | <input type="checkbox"/>            | <input type="checkbox"/> |
| 2. | Are all control measures properly maintained in effective operating condition in accordance with good engineering practices and, where applicable, manufacturer specifications? | <input checked="" type="checkbox"/> | <input type="checkbox"/>            | <input type="checkbox"/> |
| 3. | Areas of offsite sediment deposition observed?  | <input type="checkbox"/>            | <input checked="" type="checkbox"/> | <input type="checkbox"/> |

Comments: Inspected the following resources: S-IJ19, S-IJ18 and S-IJ16-B.

**Deadline:** N/A

The recommended corrective action deadline date applies to all conditions noted on this report unless otherwise noted. If listed condition(s) currently constitute non-compliance and/or corrective actions are not completed by the deadline, other enforcement actions may be issued to the entity responsible for ensuring compliance on the above project.

**Inspector Signature:** \_\_\_\_\_



**Date:** Tuesday, May 2, 2023

# FIELD INSPECTION PHOTO LOG

**Project Name:** Mountain Valley Pipeline

**Date:** Tuesday, May 2, 2023

**Figure 1: STA 11025+00** – Controls in place and functioning properly. Area stabilized with straw.



**Figure 2: STA 11041+00** – Controls in place and functioning properly. Area stabilized with straw.



**Figure 3: STA 11062+00** – Controls in place and functioning properly.



**Figure 4: STA 11084+00** – Controls in place and functioning properly.

