

FIELD INSPECTION REPORT

Project Name:	Mountain Valley Pipeline	Inspector:	Matthew Grant
Inspection Date:	Tuesday, August 22, 2023	Project Contact:	Brian Clauto
Spread G: Giles Montgomery	AR 256.02 Sta 11327+35-11340, 11498+59, 11790-11742 ATWS 633, 633A, 1487	Weather:	Dry

ACTIVE STAGE OF CONSTRUCTION: (Check all that apply)

- Tree Felling
 Clearing/Grubbing
 Grading
 Trenching
 Stringing/Welding
 Lowering/Backfilling
 Final Grading
 Temp. Stabilization
 Perm. Stabilization
 Resource Crossing

- | | Yes | No | N/A |
|------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|-------------------------------------|-------------------------------------|--------------------------|
| 1. Are controls installed and implemented in accordance with the approved erosion and sediment control plan and stormwater management plans? | <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> |
| 2. Are all control measures properly maintained in effective operating condition in accordance with good engineering practices and, where applicable, manufacturer specifications? | <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> |
| 3. Areas of offsite sediment deposition observed? | <input type="checkbox"/> | <input checked="" type="checkbox"/> | <input type="checkbox"/> |

- **Comments:** Inspected the following resources: S-NN12, S-NN13, S-PP1, S-EF62, S-EF65, S-IJ52, W-IJ46PEM8
- ECD's were in place and functioning at the designated crossing.

Routine Maintenance: *(72-Hour Deadline from Notification)*

- N/A

Ineffective Controls: *(24-Hour Deadline from Notification)*

- N/A

Recommended Corrective Action: N/A

Deadline: N/A

The recommended corrective action deadline date applies to all conditions noted on this report unless otherwise noted. If listed condition(s) currently constitute non-compliance and/or corrective actions are not completed by the deadline, other enforcement actions may be issued to the entity responsible for ensuring compliance on the above project.

Inspector Signature: _____  _____

Date: Tuesday, August 22, 2023

FIELD INSPECTION PHOTO LOG

Project Name: Mountain Valley Pipeline

Date: Tuesday, August 22, 2023

Figure 1: Designated crossing S-NN12, ECD's are in place.



Figure 2: Designated crossing S-EF62, ECD's are in place.



Figure 3: Designated Crossing S-PP1, ECD's are in place for active construction.



Figure 4: Designated crossings S-EF65, ECD's are in place.

