

FIELD INSPECTION REPORT

| | | | |
|-----------------------------|--|-------------------------|---------------|
| Project Name: | Mountain Valley Pipeline | Inspector: | Matthew Grant |
| Inspection Date: | Tuesday, September 19, 2023 | Project Contact: | Brian Clauto |
| Spread G: Montgomery | Sta 1167-11687+42, 10927+44-10930+01, 10880-10883, 11767+44 ATWS 1032, 1360, 1333, 471 | Weather: | Dry |

ACTIVE STAGE OF CONSTRUCTION: (Check all that apply)

- Tree Felling
 Clearing/Grubbing
 Grading
 Trenching
 Stringing/Welding
 Lowering/Backfilling
 Final Grading
 Temp. Stabilization
 Perm. Stabilization
 Resource Crossing

- | | Yes | No | N/A |
|--|-------------------------------------|-------------------------------------|--------------------------|
| 1. Are controls installed and implemented in accordance with the approved erosion and sediment control plan and stormwater management plans? | <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> |
| 2. Are all control measures properly maintained in effective operating condition in accordance with good engineering practices and, where applicable, manufacturer specifications? | <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> |
| 3. Areas of offsite sediment deposition observed? | <input type="checkbox"/> | <input checked="" type="checkbox"/> | <input type="checkbox"/> |

▪ **Comments:** Inspected the following resources: S-MN21, S-IJ52, W-IJ46, S-A32

Routine Maintenance: (*72-Hour Deadline from Notification*)

- N/A


Ineffective Controls: (*24-Hour Deadline from Notification*)

- N/A

Recommended Corrective Action: N/A

Deadline: N/A

The recommended corrective action deadline date applies to all conditions noted on this report unless otherwise noted. If listed condition(s) currently constitute non-compliance and/or corrective actions are not completed by the deadline, other enforcement actions may be issued to the entity responsible for ensuring compliance on the above project.

Inspector Signature: _____  _____

Date: Tuesday, September 19, 2023

FIELD INSPECTION PHOTO LOG

Project Name: Mountain Valley Pipeline

Date: Tuesday, September 19, 2023

Figure 1: Designated crossing S-MN21, active lowering & welding.



Figure 2: Bore site for S-Y2 &S-Y3 at Sta10930+01, ECD's are in place.




Figure 3: Designated crossing S-IJ52, ECD's are in place.



Figure 4: Designated crossing S-A32, ECD's are in place.

