

FIELD INSPECTION REPORT

Project Name:	Mountain Valley Pipeline	Inspector:	Matthew Grant
Inspection Date:	Monday, January 8, 2024	Project Contact:	Brian Clauto
Spread G: Giles	Sta 10989-10970, 10930-10926+11 ATWS 471 AR GI 242.01	Weather:	Wet

ACTIVE STAGE OF CONSTRUCTION: (Check all that apply)

- Tree Felling
 Clearing/Grubbing
 Grading
 Trenching
 Stringing/Welding
 Lowering/Backfilling
 Final Grading
 Temp. Stabilization
 Perm. Stabilization
 Resource Crossing

- | | Yes | No | N/A |
|--|-------------------------------------|-------------------------------------|--------------------------|
| 1. Are controls installed and implemented in accordance with the approved erosion and sediment control plan and stormwater management plans? | <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> |
| 2. Are all control measures properly maintained in effective operating condition in accordance with good engineering practices and, where applicable, manufacturer specifications? | <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> |
| 3. Areas of offsite sediment deposition observed? | <input type="checkbox"/> | <input checked="" type="checkbox"/> | <input type="checkbox"/> |

▪ **Comments:** Inspected the following resources: S-MN11, S-E25, S-E24, S-Y2, S-Y3

Routine Maintenance: (*72-Hour Deadline from Notification*)
- N/A

Ineffective Controls: (*24-Hour Deadline from Notification*)
- N/A

Recommended Corrective Action: N/A

Deadline: N/A

The recommended corrective action deadline date applies to all conditions noted on this report unless otherwise noted. If listed condition(s) currently constitute non-compliance and/or corrective actions are not completed by the deadline, other enforcement actions may be issued to the entity responsible for ensuring compliance on the above project.

Inspector Signature: _____  _____

Date: Monday, January 8, 2024

FIELD INSPECTION PHOTO LOG

Project Name: Mountain Valley Pipeline

Date: Monday, January 8, 2024

Figure 1: Designated crossing S-E25, ECD's are in place.



Figure 2: Designated crossing S-Y2. ECD's are in place for active construction.



Figure 3: Designated crossing S-E24, ECD's were being maintained.



Figure 4: Designated crossing S-MN11, ECD's are in place for active construction.

