

FIELD INSPECTION REPORT

Project Name:	Mountain Valley Pipeline	Inspector:	Matthew Grant		
Inspection Date:	Monday, January 29, 2024	Project Contact:	Brian Clauto		
Spread G: Giles	Sta 10605-10600, 10672-10670, 10710, 10860-10858, 10885, 10930- 10926 ATWS 340, 1390, 1391,471 AR GI 238, 240, 241.01, 241.04	Weather:	Wet		

ACTIVE STAGE OF CONSTRUCTION: (Check all that apply)												
	☐ Tree Felling		☐ Clearing/Grubbing			Grading		Trenching	\boxtimes	⊠ Stringing/Weld		
\boxtimes	Lowering/E	wering/Backfilling		Final Grading		Temp. Stabilization		Perm. Stabilization	\boxtimes	Res	Resource Crossing	
									Yes	No	N/A	
Are controls installed and implemented in accordance with the approved erosion and sediment control plan and stormwater management plans?							\boxtimes					
	2.	Are all control measures properly maintained in effective operating condition in accordance with good engineering practices and, where applicable, manufacturer specifications?							\boxtimes			
	3.	Areas of of	fsite s	sediment deposition ob	serve	d?				\boxtimes		
 <u>Comments:</u> Inspected the following resources: W-C3, S-A32, S-Y2, S-Y3 ECD's were in place and functioning. 												
Routine Maintenance: (<u>72-Hour Deadline</u> from Notification) - N/A												
Ineffective Controls: (24-Hour Deadline from Notification) - N/A												
Recommended Corrective Action: N/A												

Deadline: N/A

The recommended corrective action deadline date applies to all conditions noted on this report unless otherwise noted. If listed condition(s) currently constitute non-compliance and/or corrective actions are not completed by the deadline, other enforcement actions may be issued to the entity responsible for ensuring compliance on the above project.

Inspector Signature:

Date: Monday, January 29, 2024



FIELD INSPECTION PHOTO LOG

Project Name: Mountain Valley Pipeline <u>Date</u>: Monday, January 29, 2024


Figure 1: Sta 10672, lowering construction activity.



Figure 2: Sta 10605, ECD's are in place.



Figure 3: Sta 10710, ECD's are in place.



• Figure 4: Designated crossing S-A32, ECD's are in place.

