

FIELD INSPECTION REPORT

Project Name:	Mountain Valley Pipeline	Inspector:	Marshall Willis
Inspection Date:	Tuesday, February 13, 2024	Project Contact:	Brian Clauto, Cory Chalmers
Spread G: Giles County	Rt. 42 and Clover Hollow Rd. STA 11254+00 – 11257+00 MVP-MLV-AR-25	Weather:	Dry

ACTIVE STAGE OF CONSTRUCTION: (Check all that apply)

- | | | | | |
|---|--|--|--|---|
| <input type="checkbox"/> Tree Felling | <input type="checkbox"/> Clearing/Grubbing | <input type="checkbox"/> Grading | <input type="checkbox"/> Trenching | <input type="checkbox"/> Stringing/Welding |
| <input type="checkbox"/> Lowering/Backfilling | <input type="checkbox"/> Final Restoration | <input type="checkbox"/> Temp. Stabilization | <input type="checkbox"/> Perm. Stabilization | <input checked="" type="checkbox"/> Resource Crossing |


- | | Yes | No | N/A |
|--|-------------------------------------|-------------------------------------|--------------------------|
| 1. Are controls installed and implemented in accordance with the approved erosion and sediment control plan and stormwater management plans? | <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> |
| 2. Are all control measures properly maintained in effective operating condition in accordance with good engineering practices and, where applicable, manufacturer specifications? | <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> |
| 3. Areas of offsite sediment deposition observed? | <input type="checkbox"/> | <input checked="" type="checkbox"/> | <input type="checkbox"/> |

Comments: Inspected the following resources: S-RR2, W-RR1b and S-YZ6.

Deadline: N/A

The recommended corrective action deadline date applies to all conditions noted on this report unless otherwise noted. If listed condition(s) currently constitute non-compliance and/or corrective actions are not completed by the deadline, other enforcement actions may be issued to the entity responsible for ensuring compliance on the above project.

Inspector Signature:



Date: Tuesday, February 13, 2024

FIELD INSPECTION PHOTO LOG

Project Name: Mountain Valley Pipeline

Date: Tuesday, February 13, 2024

Figure 1: Rt. 42 and Clover Hollow Dr. – Head of spring located off ROW near intersection of Rt. 42 and Clover Hollow Dr.

☉ 264°W (T) ☉ 37.300783°N, 80.490614°W ±22ft ▲ 1862ft



Figure 2: Rt. 42 and Clover Hollow Dr. – Spring located off ROW near intersection of Rt. 42 and Clover Hollow Dr.

☉ 234°SW (T) ☉ 37.301159°N, 80.490341°W ±13ft ▲ 1878ft



Figure 3: Rt. 42 and Clover Hollow Dr. – Stormwater conveyance channel connecting spring and Sinking Creek.

☉ 318°NW (T) ☉ 37.301745°N, 80.490414°W ±36ft ▲ 1883ft



Figure 4: Rt. 42 and Clover Hollow Dr. – Confluence of Sinking Creek and spring.

☉ 41°NE (T) ☉ 37.308505°N, 80.495463°W ±28120ft ▲ 1152ft

