



Photo illustrates the preconstruction conditions of wetland W-N16 (September 2018)



Photo illustrates wetland W-N16 immediately following installation and backfill (September 2018).



Photo illustrates restored wetland W-N16 (August 2019)



Photo illustrates restored wetland W-N16 (June 2020)



Photo illustrates the preconstruction conditions of stream S-VV1 and wetland w-VV2.



Photo illustrates the construction conditions of stream S-VV1 and wetland w-VV2. Note that the water has been completely diverted during construction.



Photo illustrates the restored stream S-VV1 and wetland W-VV2 (August 2019)



Photo illustrates the restored stream S-VV1 and wetland W-VV2 (October 2020)



Photo illustrates the active construction of Northfork Roanoke River crossing (July, 2018)



Photo illustrates the restored crossing of Northfork Roanoke River crossing (February, 2019)



Photo illustrates the restored crossing of Northfork Roanoke River crossing (May, 2019)



Both photo illustrate Direct Pipe drill rig for the Meadow River crossing.





Photo illustrates the backfilling of the Meadow River bore pit.



Photo illustrates the final grading of the bore prior to seeding.