

FIELD INSPECTION REPORT

| | | | |
|----------------------------|--|-------------------------|---------------|
| Project Name: | Mountain Valley Pipeline | Inspector: | Matthew Grant |
| Inspection Date: | Tuesday, July 14, 2020 | Project Contact: | Brian Clauto |
| Spread G: Giles | AR GI-243.01, 249.01, 256.02, 025 ATWS 1464, 1370, 1370A MP 211.5, 212.4, 214.5, 215 | Weather: | Dry |

ACTIVE STAGE OF CONSTRUCTION: (Check all that apply)

- Tree Felling
 Clearing/Grubbing
 Grading
 Trenching
 Stringing/Welding
 Lowering/Backfilling
 Final Grading
 Temp. Stabilization
 Perm. Stabilization
 Dormant

- | | Yes | No | N/A |
|--|-------------------------------------|-------------------------------------|--------------------------|
| 1. Are controls installed and implemented in accordance with the approved erosion and sediment control plan and stormwater management plans? | <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> |
| 2. Are all control measures properly maintained in effective operating condition in accordance with good engineering practices and, where applicable, manufacturer specifications? | <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> |
| 3. Areas of offsite sediment deposition observed? | <input type="checkbox"/> | <input checked="" type="checkbox"/> | <input type="checkbox"/> |

- Comments: Inspected the following resources: S-RR04, S-NN11, S-NN12, S-NN13
- ECD's were in place at the crossing.


Routine Maintenance: (72-Hour Deadline from Notification)
- N/A

Ineffective Controls: (24-Hour Deadline from Notification)
- N/A

Recommended Corrective Action: N/A

Deadline: N/A

The recommended corrective action deadline date applies to all conditions noted on this report unless otherwise noted. If listed condition(s) currently constitute non-compliance and/or corrective actions are not completed by the deadline, other enforcement actions may be issued to the entity responsible for ensuring compliance on the above project.

Inspector Signature: _____  _____

Date: Tuesday, July 14, 2020

FIELD INSPECTION PHOTO LOG

Project Name: Mountain Valley Pipeline

Date: Tuesday, July 14, 2020


Figure 1: Near MP 211.3 area is stabilized.



Figure 2: ATWS 1464 is dormant and currently not in use



Figure 3: On AR 256.02 near designated stream S-NN11



- Figure 4: Designated stream S-NN12, ECD's are in place.

