

## FIELD INSPECTION

<b>Project Name:</b>	Mountain Valley Pipeline	<b>Inspector:</b>	Marshall Willis
<b>Inspection Date:</b>	Wednesday, November 20, 2019	<b>Project Contact:</b>	Brian Clauto, Cory Chalmers
<b>Spread G: Montgomery County</b>	STA 11327+85 – 11471+52 MVP-GI-258.01/256.02/256 ATWS 633/633A	<b>Weather (Wet/Dry/Rain):</b>	Dry

**STAGE OF CONSTRUCTION:** (Check all that apply)

- Clearing                       Rough Grading                       Trench Excavation                       Pipe Assembly, Testing & Installation  
 Backfilling and Grade Restoration                       Final Grading & Stabilization                       Other: Dormant

- |   |   | Yes                                 | No                                  | N/A                      |
|---|---|-------------------------------------|-------------------------------------|--------------------------|
| 1 | Are controls installed and implemented in accordance with the approved erosion and sediment control plan and stormwater management plans?                                       | <input checked="" type="checkbox"/> | <input type="checkbox"/>            | <input type="checkbox"/> |
| 2 | Are all control measures properly maintained in effective operating condition in accordance with good engineering practices and, where applicable, manufacturer specifications? | <input checked="" type="checkbox"/> | <input type="checkbox"/>            | <input type="checkbox"/> |
| 3 | Areas of offsite sediment deposition were observed?   | <input type="checkbox"/>            | <input checked="" type="checkbox"/> | <input type="checkbox"/> |

Comments: Inspected the following resources: S-OO12, S-OO13, S-OO14, W-CD12, S-KL43, S-NN11, S-NN12 and S-NN14.

**Recommended Corrective Action:** N/A.

**Deadline:** Within 24-hr notification

The recommended corrective action deadline date applies to all conditions noted on this report unless otherwise noted. If listed condition(s) currently constitute non-compliance and/or corrective actions are not completed by the deadline, other enforcement actions may be issued to the entity responsible for ensuring compliance on the above project.

Inspector Signature: *Marshall Willis*

Date: 11/20/2019

# FIELD INSPECTION PHOTO LOG

**Project Name:** Mountain Valley Pipeline

**Date:** Wednesday, November 20, 2019

Fig. 1: **STA 11469+60** – Controls in place and functioning properly. Area adequately stabilized with straw.



Fig. 2: **STA 11448+93** – Controls in place and functioning properly along Stream S-OO14. Area adequately stabilized with straw.



Fig. 3: **STA 11412+71** – Controls in place and functioning properly. Area adequately stabilized.



Fig. 4: **STA 11327+85** – Controls in place and functioning properly along Stream S-NN12. Area adequately stabilized with straw.

