

FIELD INSPECTION

Project Name:	Mountain Valley Pipeline	Inspector:	Matthew Grant
Inspection Date:	Thursday, October 24, 2019	Project Contact:	Brian Clauto
Spread: Craig Co. AR CR2580.01 MP217.3 St11475-11470 Giles Co. AR GI 253.02 AR GI 256.02 MP213.9-214.9 Montgomery Co. AR 266 MP225.3-223.2	Spread G	Weather (Wet/Dry/Rain):	Dry

STAGE OF CONSTRUCTION: (Check all that apply)

- Clearing Rough Grading Trench Excavation Pipe Assembly, Testing & Installation
 Backfilling and Grade Restoration Final Grading & Stabilization Other: Dormant

- | | | Yes | No | N/A |
|---|---|-------------------------------------|-------------------------------------|--------------------------|
| 1 | Are controls installed and implemented in accordance with the approved erosion and sediment control plan and stormwater management plans? | <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> |
| 2 | Are all control measures properly maintained in effective operating condition in accordance with good engineering practices and, where applicable, manufacturer specifications? | <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> |
| 3 | Areas of offsite sediment deposition were observed? | <input type="checkbox"/> | <input checked="" type="checkbox"/> | <input type="checkbox"/> |


Comments:

- Inspected designated streams and wetlands included: S-NN11, S-NN12, S-K43
- ECD's were in place and functioning at the designated crossings.

Recommend Corrective Action: N/A

Deadline: N/A

The recommended corrective action deadline date applies to all conditions noted on this report unless otherwise noted. If listed condition(s) currently constitute non-compliance and/or corrective actions are not completed by the deadline, other enforcement actions may be issued to the entity responsible for ensuring compliance on the above project.

Inspector Signature:  Date: 11-15-19

FIELD INSPECTION PHOTO LOG

Project Name: Mountain Valley Pipeline

Date: Thursday, October 24, 2019

- Fig. 1 Designated stream S-NN12, ECD's in place and functioning.



- Fig. 2 Designated stream S-NN11, ECD's in place and functioning.



- Fig. 3 Near MP 224.4 temp/permanent waterbars have been installed



- Fig. 4 Near MP 223.2 are has been stabilized.

