

FIELD INSPECTION

Project Name:	Mountain Valley Pipeline	Inspector:	Matthew Grant
Inspection Date:	Thursday, December 20, 2018	Project Contact:	Brian Clauto
Spread: Giles County AR GI 234 Designated stream SQ14	Spread G	Weather (Wet/Dry/Rain):	Wet

STAGE OF CONSTRUCTION: (Check all that apply)

- ☐ Clearing

☐ Rough Grading

☐ Trench Excavation

☐ Pipe Assembly, Testing & Installation

☐ Backfilling and Grade Restoration

☐ Final Grading & Stabilization

☒ Other: Access Road

- | | | Yes | No | N/A |
|---|---|-------------------------------------|--------------------------|--------------------------|
| 1 | Are controls installed and implemented in accordance with the approved erosion and sediment control plan and stormwater management plans? | <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> |
| 2 | Are all control measures properly maintained in effective operating condition in accordance with good engineering practices and, where applicable, manufacturer specifications? | <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> |
| 3 | Areas of offsite sediment deposition were observed? | <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> |

Comments:

- Access Road GI 234 rock lined channel appears to be functioning; vertical cut ditch walls have had matting installed. Designated stream SQ14 shows signs of sediment and possibly road gravel in the stream.

Recommended Corrective Action: Submit amended plans for GI 234 access road to DEQ for approval; remove sediment and road gravel on SQ 14 per property owner approval.

Deadline: n/a

The recommended corrective action deadline date applies to all conditions noted on this report unless otherwise noted. If listed condition(s) currently constitute non-compliance and/or corrective actions are not completed by the deadline, other enforcement actions may be issued to the entity responsible for ensuring compliance on the above project.

Inspector Signature: Matthew Grant Date: 1/3/19

FIELD INSPECTION PHOTO LOG

Project Name: Mountain Valley Pipeline

Date: Thursday, December 20, 2018

- Fig. 1 AR GI 234 rock lined channel ditch have been matted.



- Fig. 2 ECD's in place on AR GI 234

