

## **FIELD INSPECTION**

Project Name:	Mountain Valley Pipeline	Inspector:	Matthew Grant
Inspection Date:	Wednesday, November 28, 2018	Project Contact:	Brian Clauto
Spread: Giles County AR GI 234 Designated stream SQ14	Spread G	Weather (Wet/Dry/Rain):	Wet
STAGE OF CONSTRUCT	ION: (Check all that apply)		
Clearing	Rough Grading	Trench Excavation	Pipe Assembly, Testing & Installation
Backfilling and Grade	e Restoration Final Grading	3 & Stabilization	Other: Access Road
		Yes No N/A	
	d and implemented in accordance with the nt control plan and stormwater managem		
2 condition in accorda	sures properly maintained in effective ope ance with good engineering practices and cturer specifications?		
3 Areas of offsite sedi	ment deposition were observed?		
Comments:  Access Road GI 234 rock lined channel appears to be functioning; vertical cut ditch walls are not stabilized. Designated stream SQ14 shows signs of sediment and possibly road gravel in the stream.  Recommended Corrective Action: Submit amended plans for GI 234 access road to DEQ for approval; remove sediment and road gravel on SQ 14 per property owner approval.			
	action deadline date applies to all conditions rd/or corrective actions are not completed by the bove project.		se noted. If listed condition(s) currently ons may be issued to the entity responsible for



## FIELD INSPECTION PHOTO LOG

Project Name: Mountain Valley Pipeline Date: Wednesday, November 28, 2018






Fig. 2 ECD's in place on AR GI 234



Fig. 3 Designated stream SQ 14 has signs of road gravel in stream.

