

FIELD INSPECTION

Project Name:	Mountain Valley Pipeline	Inspector:	Matthew Grant
Inspection Date:	Tuesday, November 27, 2018	Project Contact:	Brian Clauto
Spread: Giles County MP207 St#10933+32 MP217 St#11471-11456 MP222 St#11769-11757	Spread G	Weather (Wet/Dry/Rain):	Wet

STAGE OF CONSTRUCTION: (Check all that apply)

- Clearing Rough Grading Trench Excavation Pipe Assembly, Testing & Installation
 Backfilling and Grade Restoration Final Grading & Stabilization Other: dormant

- | | | Yes | No | N/A |
|---|---|-------------------------------------|--------------------------|--------------------------|
| 1 | Are controls installed and implemented in accordance with the approved erosion and sediment control plan and stormwater management plans? | <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> |
| 2 | Are all control measures properly maintained in effective operating condition in accordance with good engineering practices and, where applicable, manufacturer specifications? | <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> |
| 3 | Areas of offsite sediment deposition were observed? | <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> |

Comments:

- St#10933+32 No sediment observed off the ROW, controls in place and functioning.
- St#11459+00 No sediment observed off the ROW, controls in place and functioning.
- St#11757+00 Sediment off the ROW, controls had been repaired and were functioning.
- St#11764+00 No sediment observed off the ROW, controls in place and functioning.
- St#11769+00 No sediment observed off the ROW, controls in place and functioning.
-

Recommended Corrective Action: remove sediment per owner approval

Deadline: Within 24hr notification

The recommended corrective action deadline date applies to all conditions noted on this report unless otherwise noted. If listed condition(s) currently constitute non-compliance and/or corrective actions are not completed by the deadline, other enforcement actions may be issued to the entity responsible for ensuring compliance on the above project.

Inspector Signature: Matthew Grant Date: 12-11-18

FIELD INSPECTION PHOTO LOG

Project Name: Mountain Valley Pipeline

Date: Tuesday, November 27, 2018

Fig. 1 At St#10933+32 no sediment observed off the ROW



Fig. 2 At St#11459+00 no sediment observed off the ROW



Fig. 3 St#11757+00 sediment off ROW



Fig. 4 St#11764 no sediment observed off the ROW



FIELD INSPECTION PHOTO LOG

Project Name: Mountain Valley Pipeline

Date: Tuesday, November 27, 2018

- Fig. 5 At St#11769+00 no sediment observed off the ROW

