

FIELD INSPECTION

Project Name:	Mountain Valley Pipeline	Inspector:	Matthew Grant
Inspection Date:	Wednesday, October 10, 2018	Project Contact:	Brian Clauto
Spread: Craig County MP 214 St#11329- 11328+60	Spread G	Weather (Wet/Dry/Rain):	Rainy

STAGE OF CONSTRUCTION: (Check all that apply)

- Clearing Rough Grading Trench Excavation Pipe Assembly, Testing & Installation
 Backfilling and Grade Restoration Final Grading & Stabilization Other: No Activity per the FERC

- | | | Yes | No | N/A |
|---|---|-------------------------------------|-------------------------------------|--------------------------|
| 1 | Are controls installed and implemented in accordance with the approved erosion and sediment control plan and stormwater management plans? | <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> |
| 2 | Are all control measures properly maintained in effective operating condition in accordance with good engineering practices and, where applicable, manufacturer specifications? | <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> |
| 3 | Areas of offsite sediment deposition were observed? | <input type="checkbox"/> | <input checked="" type="checkbox"/> | <input type="checkbox"/> |

Comments:

- **Area 1** –MP 214 St#11329 through St#11328+60 waterbars and sumps in place and functioning.

Deadline: N/A

The recommended corrective action deadline date applies to all conditions noted on this report unless otherwise noted. If listed condition(s) currently constitute non-compliance and/or corrective actions are not completed by the deadline, other enforcement actions may be issued to the entity responsible for ensuring compliance on the above project.

Inspector Signature: Matthew Grant Date: 11-8-18

FIELD INSPECTION PHOTO LOG

Project Name: Mountain Valley Pipeline

Date: Wednesday, October 10, 2018

<p>Fig. 1 At edge of access rd 256.02</p> <div style="text-align: center; background-color: black; color: white; padding: 5px;"> East Elevation </div> <div style="background-color: black; color: white; padding: 2px;"> ⚙ 264°W (T) ● 37°18'1"N, 80°28'18"W ±32.8ft ▲ 2163ft </div> 	<p>Fig. 2 At St#11329 waterbar in place</p> <div style="text-align: center; background-color: black; color: white; padding: 5px;"> South Elevation </div> <div style="background-color: black; color: white; padding: 2px;"> ⚙ 353°N (T) ● 37°18'2"N, 80°28'19"W ±16.4ft ▲ 2159ft </div> 
<p>Fig. 4 Stabilized area above St#11328+60</p> <div style="text-align: center; background-color: black; color: white; padding: 5px;"> North East Elevation </div> <div style="background-color: black; color: white; padding: 2px;"> ⚙ 239°SW (T) ● 37°18'2"N, 80°28'21"W ±16.4ft ▲ 2166ft </div> 	