

FIELD INSPECTION

FIELD INSPECTION			
Project Name:	Mountain Valley Pipeline	Inspector:	Matthew Grant
Inspection Date:	Thursday, June 13, 2019	Project Contact:	Brian Clauto
Spread: Montgomery County MP219-220 MP223	Spread G	Weather (Wet/Dry/Rain):	Dry
STAGE OF CONSTRUCT	ION: (Check all that apply)		
Clearing		Trench Excavation	Pipe Assembly, Testing & Installation
Backfilling and Grad	e Restoration	& Stabilization	Other: Dormant
-		Yes No N/A	
Are controls installed and implemented in accordance with the approved \square \square erosion and sediment control plan and stormwater management plans?			
2 condition in accorda	sures properly maintained in effective oper ance with good engineering practices and, cturer specifications?	rating 🗵 🗆 🗆 , where	
3 Areas of offsite sed	iment deposition were observed?		
Comments: Designated streams inspected included: S-006, S-RR13, S-RR14 Controls in place between 11600+92 through 11613+85			
Recommended Corrective Action: N/A			
Deadline: _N/A			
The recommended corrective constitute non-compliance an ensuring compliance on the a		oted on this report unless otherwis e deadline, other enforcement acti	se noted. If listed condition(s) currently ons may be issued to the entity responsible for

Page 1 of 2

__ Date: <u>6-24-19</u>

Inspector Signature:___



FIELD INSPECTION PHOTO LOG

Project Name: Mountain Valley Pipeline Date:Thursday, June 13, 2019

Fig. 1. ECD controls in place for designated stream S-006



Fig. 2. ECD controls in place for designated stream S-RR13



 Fig. 3. ECD controls in place for designated stream S-RR14



Fig. 4. Near MP 223 tractor for disking of soil on site

