

## FIELD INSPECTION

<b>Project Name:</b>	Mountain Valley Pipeline	<b>Inspector:</b>	Matthew Grant
<b>Inspection Date:</b>	Tuesday, June 18, 2019	<b>Project Contact:</b>	Brian Clauto
<b>Spread: Montgomery County MP223 11788-11900 AR266.03</b>	Spread G	<b>Weather (Wet/Dry/Rain):</b>	Dry

**STAGE OF CONSTRUCTION:** (Check all that apply)

- Clearing                       Rough Grading                       Trench Excavation                       Pipe Assembly, Testing & Installation  
 Backfilling and Grade Restoration                       Final Grading & Stabilization                       Other: Dormant

- |   |   | Yes                                 | No                                  | N/A                      |
|---|---|-------------------------------------|-------------------------------------|--------------------------|
| 1 | Are controls installed and implemented in accordance with the approved erosion and sediment control plan and stormwater management plans?                                       | <input checked="" type="checkbox"/> | <input type="checkbox"/>            | <input type="checkbox"/> |
| 2 | Are all control measures properly maintained in effective operating condition in accordance with good engineering practices and, where applicable, manufacturer specifications? | <input type="checkbox"/>            | <input checked="" type="checkbox"/> | <input type="checkbox"/> |
| 3 | Areas of offsite sediment deposition were observed?   | <input checked="" type="checkbox"/> | <input type="checkbox"/>            | <input type="checkbox"/> |

Comments:

- Check dams on AR 266.03 require maintenance
- Access Rd gravel was offsite and was being removed at the time of the inspection.

**Recommended Corrective Action:** Maintain all controls per the approved plan and specs

**Deadline:** Within 24hr notification

The recommended corrective action deadline date applies to all conditions noted on this report unless otherwise noted. If listed condition(s) currently constitute non-compliance and/or corrective actions are not completed by the deadline, other enforcement actions may be issued to the entity responsible for ensuring compliance on the above project.

Inspector Signature: Matthew Grant Date: 6-24-19

## FIELD INSPECTION PHOTO LOG

**Project Name:** Mountain Valley Pipeline

**Date:** Tuesday, June 18, 2019

Fig. 1. Check dam on AR 266.03 requires maintenance



Fig. 2. Check dams on AR 266.03 requires maintenance



Fig. 3. Repairs and offsite gravel removal being conducted on AR 266.03



Fig. 4.