

FIELD INSPECTION

Project Name:	Mountain Valley Pipeline	Inspector:	Marshall Willis
Inspection Date:	Friday, May 31, 2019	Project Contact:	Brian Clauto
Spread G: Giles County Montgomery County	STA 11844+91 – 11900+00 Laydown Yard 028 Laydown Yard 029 MVP-GI-238	Weather (Wet/Dry/Rain):	Dry

STAGE OF CONSTRUCTION: (Check all that apply)

- Clearing Rough Grading Trench Excavation Pipe Assembly, Testing & Installation
 Backfilling and Grade Restoration Final Grading & Stabilization Other: Dormant

- | | | Yes | No | N/A |
|---|---|-------------------------------------|-------------------------------------|--------------------------|
| 1 | Are controls installed and implemented in accordance with the approved erosion and sediment control plan and stormwater management plans? | <input type="checkbox"/> | <input checked="" type="checkbox"/> | <input type="checkbox"/> |
| 2 | Are all control measures properly maintained in effective operating condition in accordance with good engineering practices and, where applicable, manufacturer specifications? | <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> |
| 3 | Areas of offsite sediment deposition were observed? | <input type="checkbox"/> | <input checked="" type="checkbox"/> | <input type="checkbox"/> |

Comments:

Laydown Yard 029: Properly cover/store materials per PSS&S and SWPPP.
Laydown Yard 029: Clean up trash within LY.

Recommended Corrective Action: Properly store construction materials per PSS&S and SWPPP.

Deadline: Within 24-hr notification

The recommended corrective action deadline date applies to all conditions noted on this report unless otherwise noted. If listed condition(s) currently constitute non-compliance and/or corrective actions are not completed by the deadline, other enforcement actions may be issued to the entity responsible for ensuring compliance on the above project.

Inspector Signature: *Marshall Willis*

Date: 05/31/2019

FIELD INSPECTION PHOTO LOG

Project Name: Mountain Valley Pipeline

Date: Friday, May 31, 2019

Fig. 1: STA 11823+00 – Controls in place. Area stabilized.



Fig. 2: Laydown Yard 028 – Controls in place.



Fig. 3: Laydown Yard 029 – Properly store fertilizer per SWPPP.



Fig. 4: Laydown Yard 029 – Clean up/remove litter from yard.

