

## **FIELD INSPECTION**

			T
Project Name:	Mountain Valley Pipeline	Inspector:	Matthew Grant
Inspection Date:	Wednesday, April 3, 2019	Project Contact:	Brian Clauto
Spread: Montgomery County MP222-225 AR 266.03 St11767-11905	Spread G	Weather (Wet/Dry/Rain):	Dry
STAGE OF CONSTRUCTION: (Check all that apply)			
Clearing	Rough Grading	Trench Excavation	Pipe Assembly, Testing & Installation
Backfilling and Grade	e Restoration	& Stabilization	Other: Dormant
		Yes No N/A	
	d and implemented in accordance with the nt control plan and stormwater management		
2 condition in accorda	sures properly maintained in effective oper ance with good engineering practices and, cturer specifications?		
3 Areas of offsite sedi	ment deposition were observed?		
<b>-</b>			
Comments: Streams / wetlands inspected included: WIJ-10, S-IJ52 ECD's and stabilization are functioning between St#11767-11905			
Recommended Corrective Action: N/A			
<u>Deadline:</u> _N/A			
The recommended corrective action deadline date applies to all conditions noted on this report unless otherwise noted. If listed condition(s) currently constitute non-compliance and/or corrective actions are not completed by the deadline, other enforcement actions may be issued to the entity responsible for ensuring compliance on the above project.			
Inspector Signature: Date: Date:			



## FIELD INSPECTION PHOTO LOG

Project Name: Mountain Valley Pipeline Date: Wednesday, April 3, 2019





Fig. 3 St#11905+37 permanently graded area

