

FIELD INSPECTION PHOTO LOG

Project Name: Mountain Valley Pipeline

Date: Thursday, March 21, 2019

- Fig. 1 Near St#11932+54 permanent waterbar has been installed and area has been stabilized



- Fig. 2 At karsts feature 226.42, ECD's are in place and functioning



- Fig. 3 Near St#11979+30 ECD's are in place and functioning

