

FIELD INSPECTION REPORT

Project Name:	Mountain Valley Pipeline	Inspector:	Matthew Grant
Inspection Date:	Monday, June 7, 2021	Project Contact:	Brian Clauto
Spread G: Giles	AR 241.01 ATWS 469, 1334, 1056, 464 St10749-10802	Weather:	Dry

ACTIVE STAGE OF CONSTRUCTION: (Check all that apply)

- Tree Felling
 Clearing/Grubbing
 Grading
 Trenching
 Stringing/Welding
 Lowering/Backfilling
 Final Grading
 Temp. Stabilization
 Perm. Stabilization
 Dormant

	Yes	No	N/A
1. Are controls installed and implemented in accordance with the approved erosion and sediment control plan and stormwater management plans?	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
2. Are all control measures properly maintained in effective operating condition in accordance with good engineering practices and, where applicable, manufacturer specifications?	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
3. Areas of offsite sediment deposition observed?	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>

- Comments: Inspected the following resources: S-G35, S-S4, S-Z9, S-Z7, S-Z13
- ECD's were in place and functioning at the designated crossings for active construction.

Routine Maintenance: *(72-Hour Deadline from Notification)*

- N/A


Ineffective Controls: *(24-Hour Deadline from Notification)*

- Uncontained trash at St 10749+50

Recommended Corrective Action: Maintain and install all controls per the approved PSS&S.

Deadline: Within 24-Hour of Notification

The recommended corrective action deadline date applies to all conditions noted on this report unless otherwise noted. If listed condition(s) currently constitute non-compliance and/or corrective actions are not completed by the deadline, other enforcement actions may be issued to the entity responsible for ensuring compliance on the above project.

Inspector Signature: _____  _____

Date: Monday, June 7, 2021

FIELD INSPECTION PHOTO LOG

Project Name: Mountain Valley Pipeline

Date: Monday, June 7, 2021

Figure 1: Designated crossing S-G35 ECD's are in place.



Figure 2: Uncontained trash at St10749+50



Figure 3: Designated crossing S-Z7, ECD's are in place.



Figure 4: ECD's are in place and pipe is strung near St10789.

