

FIELD INSPECTION REPORT

| | | | |
|----------------------------|--|-------------------------|---------------|
| Project Name: | Mountain Valley Pipeline | Inspector: | Matthew Grant |
| Inspection Date: | Tuesday, May 4, 2021 | Project Contact: | Brian Clauto |
| Spread G: Giles | ST11025-10928 ATWS 1145, 1146 AR 244 | Weather: | Dry |

ACTIVE STAGE OF CONSTRUCTION: (Check all that apply)

- Tree Felling
 Clearing/Grubbing
 Grading
 Trenching
 Stringing/Welding
 Lowering/Backfilling
 Final Grading
 Temp. Stabilization
 Perm. Stabilization
 Dormant

- | | Yes | No | N/A |
|--|-------------------------------------|-------------------------------------|--------------------------|
| 1. Are controls installed and implemented in accordance with the approved erosion and sediment control plan and stormwater management plans? | <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> |
| 2. Are all control measures properly maintained in effective operating condition in accordance with good engineering practices and, where applicable, manufacturer specifications? | <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> |
| 3. Areas of offsite sediment deposition observed? | <input type="checkbox"/> | <input checked="" type="checkbox"/> | <input type="checkbox"/> |

- Comments: Inspected the following resources: S-IJ19, S-RR5/PA07, S-E25, S-E20, S-Y2, S-Y3
- ECD's were in place and functioning at the designated crossings.


Routine Maintenance: (72-Hour Deadline from Notification)
- N/A

Ineffective Controls: (24-Hour Deadline from Notification)
- N/A

Recommended Corrective Action: N/A

Deadline: N/A

The recommended corrective action deadline date applies to all conditions noted on this report unless otherwise noted. If listed condition(s) currently constitute non-compliance and/or corrective actions are not completed by the deadline, other enforcement actions may be issued to the entity responsible for ensuring compliance on the above project.

Inspector Signature: _____  _____

Date: Tuesday, May 4, 2021

FIELD INSPECTION PHOTO LOG

Project Name: Mountain Valley Pipeline

Date: Tuesday, May 4, 2021

Figure 1: Above designated crossing S-RR5/ PA07, ECD's are in place for active construction.

North West Elevation

☉ 118°SE (T) ● 37°19'26"N, 80°33'22"W ±32ft ▲ 2453ft



Figure 2: Active installation of CWD near St10977.

South East Elevation

☉ 300°NW (T) ● 37°19'35"N, 80°34'4"W ±328ft ▲ 2416ft



Figure 3: Protected area neat St 10965+51

South West Elevation

☉ 41°NE (T) ● 37°19'38"N, 80°34'17"W ±98ft ▲ 2234ft




Figure 4: Actively grading near St10955

South East Elevation

☉ 301°NW (T) ● 37°19'42"N, 80°34'30"W ±16ft ▲ 2232ft

